

Extended Grease Point

Innovation Purpose

On RDS dump trucks, the floor chain bearings on the rear of the truck were not getting greased because it was very hard to access the grease fitting, causing bearing failure.

Innovation Description

We purchased an extended grease gun hose and installed it on the bearing, then fastened it to the rear fender to make greasing the bearing much easier.

Implementation Date

August 2018



Innovation Highlights

It saves money because the bearings will last longer because they are being maintained properly, and saves time because the trucks will not be down for repairs

Division/District

District 1





INNOVATION  **CHALLENGE**